

## ОСНОВНЫЕ ТЕХНИЧЕСКИЕ ПАРАМЕТРЫ >



|           | Диаметр планшайбы [мм] |      |      |      |      |      |      |      |      |      |  |
|-----------|------------------------|------|------|------|------|------|------|------|------|------|--|
|           | 800                    | 1000 | 1250 | 1600 | 2000 | 2500 | 3000 | 4000 | 5000 | 6000 |  |
| BASICTURN |                        |      | >    | >    | >    | >    | >    | >    |      |      |  |
| POWERTURN | >                      | >    | >    | >    | >    | >    | >    | >    | >    |      |  |
| EXPERTURN | >                      | >    | >    | >    | >    | >    | >    | >    | >    |      |  |
| FORCETURN |                        |      |      |      |      | >    | >    | >    | >    | >    |  |



|           | Максимальный диаметр детали [мм] |      |      |      |      |      |      |      |      |      |  |
|-----------|----------------------------------|------|------|------|------|------|------|------|------|------|--|
|           | 800                              | 1000 | 1250 | 1600 | 2000 | 2500 | 3000 | 4000 | 5000 | 6000 |  |
| BASICTURN |                                  |      | 1400 | 2000 | 2300 | 2900 | 3600 | 5000 |      |      |  |
| POWERTURN | 1000                             | 1400 | 1400 | 2000 | 2300 | 2900 | 3600 | 5000 | 5800 |      |  |
| EXPERTURN | 1000                             | 1400 | 1400 | 2000 | 2300 | 2900 | 3600 | 5000 | 5800 |      |  |
| FORCETURN |                                  |      |      |      |      | 2900 | 3600 | 5000 | 6300 | 7300 |  |



|           | Максимальный вес детали [кг] |      |      |       |       |       |       |       |       |        |  |
|-----------|------------------------------|------|------|-------|-------|-------|-------|-------|-------|--------|--|
|           | 800                          | 1000 | 1250 | 1600  | 2000  | 2500  | 3000  | 4000  | 5000  | 6000   |  |
| BASICTURN |                              |      |      |       |       | 8000  | 12000 | 20000 | 25000 | 25000  |  |
| POWERTURN | 4000                         | 6500 | 8000 | 12000 | 20000 | 25000 | 30000 | 30000 | 30000 |        |  |
| EXPERTURN | 4000                         | 6500 | 8000 | 12000 | 20000 | 25000 | 30000 | 30000 | 30000 |        |  |
| FORCETURN |                              |      |      |       |       | 45000 | 45000 | 60000 | 80000 | 100000 |  |



|           | Максимальное количество оборотов планшайбы [об/мин] |      |      |      |      |      |      |      |      |      |  |
|-----------|---|------|------|------|------|------|------|------|------|------|--|
|           | 800   | 1000 | 1250 | 1600 | 2000 | 2500 | 3000 | 4000 | 5000 | 6000 |  |
| BASICTURN |   |      | 630  | 400  | 315  | 250  | 200  | 150  |      |      |  |
| POWERTURN | 630   | 630  | 630  | 400  | 315  | 250  | 200  | 150  | 125  |      |  |
| EXPERTURN | ИНДИВИДУАЛЬНЫЙ ПОДХОД В РАБОТЕ                      |      |      |      |      |      |      |      |      |      |  |
| FORCETURN |   |      |      |      |      | 250  | 200  | 150  | 125  | 100  |  |



|           | Максимальная высота детали [мм] |      |      |      |      |      |      |      |      |      |  |
|-----------|---------------------------------|------|------|------|------|------|------|------|------|------|--|
|           | 800                             | 1000 | 1250 | 1600 | 2000 | 2500 | 3000 | 4000 | 5000 | 6000 |  |
| BASICTURN |                                 |      | 1900 | 2000 | 2000 | 2540 | 2540 | 2480 |      |      |  |
| POWERTURN | 1300                            | 1800 | 1800 | 2500 | 2500 | 3140 | 3140 | 3080 | 3080 |      |  |
| EXPERTURN | 1300                            | 1800 | 1800 | 2500 | 2500 | 3140 | 3140 | 3080 | 3080 |      |  |
| FORCETURN |                                 |      |      |      |      | 4000 | 4000 | 5000 | 5000 | 5000 |  |